







JB6089

 52-16-140

 46

SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL





JB6092

 54-16-138

 42

SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL





JB6090

 54-17-138

 40

SPRING



C1



C2



C3



C4




C5

ACETATE  
+METAL





JB6082

 57-16-145

 44

SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL




JB6084

 54-18-140

 44

SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL






JB6091

 54-16-138

 41

SPRING



C1



C2



C3



C4



C5





JB6093

 54-17-138

 46

SPRING



C1



C2



C3



C4



C5






JB6033

 55-17-145



SPRING



C1



C2



C3




C4

ACETATE  
+METAL




JB6080

 52-21-145

 43

HINGE



C1



C2



C2



C3




C4



C5






JB6087

 53-16-140

 39

SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL



JB6081

 57-16-145

 40

SPRING



C1



C2



C3




C4



C5





JB6065

 52-20-140



SPRING



C1



C2



C3



C4



C5




JB6025

 49-20-138



HING



C1-1



C1-2



C2



C3




C4



C5






JB6058

 55-16-145



SPRING



C1



C2



C3



C5





JB6029

 55-20-145



SPRING



C1



C2



C3



C4



C6

ACETATE+  
METAL





JB6083

52-19-142

43

HINGE



C1



C2



C3




C4



C5






JB6078

 52-20-135

 43

SPRING



C1



C2



C3



C4



C5



C6

ACETATE  
+METAL





JB6071

 54-17-145

 41

HINGE



C1



C2



C3



C4



C5

ACETATE  
+METAL




JB-7007

54-19-140

38

HINGE



C2



C3



C4



C5





JB6028

 55-19-145



SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL




JB6059

 54-17-140

 44

SPRING



C1



C2



C3-1




C4-1



C5






JB6076

 48-20-138

 41

SPRING



C1



C2



C3



C4



C5



C6

ACETATE  
+METAL



JB6062

51-21-145

45

SPRING



C1



C2



C3




C4



C5





JB6077

 52-18-138

 44

SPRING



C1



C2



C3



C4



C5




JB6077-1

52-18-138

44

SPRING



C1



C4



C5




JB6079

 54-18-140

 39

SPRING



C1



C2



C3



C4




C5

ACETATE  
+METAL




JB6070

 56-16-140

 40

SPRING



C1



C3



C4



JB-7004

52-19-138



SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL






JB-7005

53-15-135



SPRING



C1



C2



C3



C4

ACETATE  
+METAL





JB-7006

 51-20-138



SPRING



C1



C3



C4

ACETATE  
+METAL




JB6032

 54-19-145



SPRING




C2



C3



JB6066

 53-20-146



SPRING



C1



C2



C3



C4



C5






JB6064

 55-19-145



SPRING




C3



C5





JB6072

 52-18-140



SPRING



C1



C2




C3



C4






JB6075

 53-17-137



SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL





JB7002

 52-20-138



SPRING



C1



C2




C3

ACETATE  
+METAL




JB7003

 50-16-138



SPRING



C1



C2




C3

ACETATE  
+METAL




JB-7001

 52-17-138



HINGE



C1



C2



C3




C4



C5





JB6069

 54-18-145



HINGE



C1



C2-1



C3



C4



C5

ACETATE  
+METAL





JB6061

 55-19-145



HINGE



C1



C2



C3



C4



C4-1



C5

ACETATE  
+METAL



JB6060

 54-19-145



SPRING



C2



C3



C4



C5

ACETATE  
+METAL





JB6056-2

54-16-142



SPRING



C1



C3



C4

ACETATE  
+METAL





JB6054

 55-16-140



SPRING



C1



C2



C3



C4



C5

ACETATE  
+METAL






JB6051

51-19-138



HINGE



C1



C2



C3



C4




C5

ACETATE  
+METAL





JB6048

 52-17-140



SPRING



C1



C2



C3



C4

ACETATE  
+METAL





JB6047

52-16-138



SPRING



C1




C2



C3






JB6046

 52-16-138



SPRING



C4



C6-1



ACETATE  
+METAL





JB6035

52-15-142



SPRING



C1



C6

ACETATE  
+METAL




JB6034

55-16-145



SPRING



C1



C3



C4



C5






ACETATE  
+METAL

JB6031

 54-17-145



SPRING




C2

ACETATE  
+METAL





JB6027

 52-18-138



HINGE



C3




JB6025

 49-20-138



HING



C1-1



C1-2



C2



C4




C5

ACETATE  
+METAL





JB6021

 48-21-135



SPRING



C1



C2




C3

ACETATE  
+METAL






JB6020

 54-18-138



SPRING



C1




C2



C5




JB6019

 52-21-138



HING



C1



C2



C4




C5

ACETATE  
+METAL




JB6015

 52-20-138



SPRING




C1



C4






JB6073

 53-16-140



SPRING



C1



C3





JB6011

52-17-142

44

SPRING



C2



C3



C4





ACETATE  
+METAL

JB6009

53-16-140



SPRING



C1



C5

ACETATE  
+METAL



JB6003

52-17-142



SPRING



C1



C2



C2-1



C3



C4



C5